

NARRATIVE SECTION

Study Unit	Other	Date Of Construction: <u>1914</u>
<u>Architecture/Landscape Architecture</u>		Architect:
		Builder:
		Engineer:

Property appears to meet criteria for the National Register of Historic Places: No
Property is located in a historic district (National and/or local): No
Property potentially contributes to a historic district (National and/or local):

Statement of Significance The house is a good example of the Craftsman style located on the East Side of Olympia on a double lot. The house retains all of its historic features and includes on the property a distinctive stepped garage on the north side. John and Annie Sanderson lived in the house from the time it was built for a number of years.

Description of Physical Appearance Historic features: 1. One and one-half story Craftsman style front gable house set on a concrete foundation. 2. Narrow clapboard cladding on the main body of the house and shingles in the gables. The clapboard flares slightly at the base of the house. 3. Wide, bracketed eaves with fascia boards and exposed rafter ends. 4. A large, gable-roof dormer is on the south side of the house. 5. A square dormer with four sash windows is also on the south side. 6. A tripartite window flanks the front porch. 7. A gable roofed porch with similar detailing to the main body of the house extends from the west side and is supported by large square posts. The original front door and lighting fixture are still extant. 8. Other windows are one over one double hung sash. Additions: The rear porch has been altered and new windows installed.

Major Bibliographic References Sources: Pioneer Title Company records and Polk City Directories

PHOTOS



View of East Facade
taken 9/1/1997
Photography Neg. No. (Roll No./Frame No.):
43-19
Comments: